

Notice

SANYO

- ☐ CORRECTION ☒ PRODUCTION CHANGE
☐ SERVICE FLASH ☐ ADD INFORMATION

FILE NO.

REVISION 2

Please add this notice to the Service Manual listed below.

Category : COLOR TELEVISION	Date: NOVEMBER / 15 / 2007
Model: DP19657	Effective from : Chassis No. P19657-02
Destination: U.S.A. / CANADA	REF : No. SM780148-02

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P19657-00. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P19657-00 used in Model DP19657 (SM7800148).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. **088 OP2 Data** should be changed from **02h** to **00h** in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

- A : Misprint B : Quality Reliability C : Standardization
D : Design E : Add as a possible sub F : Schematic location change
G : Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchangeability	Reason
Page 24, Chassis Electrical Parts List	⚠ EL901	Old	1AV4T40B83300	LCD (M190A1-L02)	1	NO	D
		New	1AV4T40B93100	LCD (M190MWW1-201)	1	NO	

For parts or service contact

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000

November 2007 SMC

Published in U.S.A.

DP19657, N4TM, PRODUCT CODE 113013504

REFERENCE No. SM780148-02